

## Under Review Notification

**Raised By:** Mike Lee

**Product #:** N/A

**Date:** July 09, 2018

**Product Name:** PCM Adapter Kit

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	IPP Under Review	Product Specifications Under Review ("Bluefiles")		
RBW2905G00132-3G	RBW2905G00132-3G Rev. 2	Y	Y	Y	Y	Y	N	N	18-766	SEE BELOW
RBW2905G00232-3G-1/-3/ -5/-7/-9/-11/-13/-15/-17	RBW2905G00232-3G Rev.2	Y	Y	Y	Y	Y	N	N	18-766	
RBW2905G00332-3G-1/-3 -5/-7/-9/-11/-13/-15	RBW2905G00332-3G Rev. 2	Y	Y	Y	Y	Y	N	N	18-766	

**Description of Issue:**

Tool failed while in use at 3000psi.

Please advise customers to quarantine all tools that were manufactured in Hawkesbury.

It appears that the when this kit was sold from Red Barn the affected part was procured from Tronair and resold by Red Barn.

Drawing is lacking torque values and pressure test info

Please hold shipment until tool design is confirmed by Engineering

Contact Mike Lee with any questions

**Distribution:**

VP Operations

Director of Operations

Director Quality Assurance

QC Coordinator

Director of Engineering

Chief Engineer

Engineering Project Managers

Engineering Clerk

Customer Support Manager

Production Engineers

Production Planners

Purchasing Manager

Technical Support

Product Manager - Solutions Provider

Supply Chain Director

Marketing Eugene